

## SERVICE BULLETIN

<input type="checkbox"/>	Action Required
<input checked="" type="checkbox"/>	Only If Encountered
<input type="checkbox"/>	Information Only

**To:** All Dealers and Customers  
**Bulletin Number:** B170007A-16  
**Date:** 26-May-2017  
**Brands:** WeedEater  
**Product:** Gas blowers  
**Dates Produced:** Prior to May 3, 2017  
**Affected Market(s):** North America

### Description/Background:

The starter pulley can become misshaped when experiencing elevated temperatures during starting of the unit.

### Action Required:

- Units not yet sold to consumers are not approved for this service; service is required only if the issue is encountered on a customer's unit.
- Service includes replacing the pulley.
- Normal warranty applies.

### Warranty Reporting:

Must perform service through Husqvarna's warranty process using only this information:

- Component code: **227 – Starter pulley**
- Defect code: **92 – Part exchanged on request by Husqvarna**
- Warranty type: **1 – warranty**
- Time Units: **4 units (24 minutes)**

### Part Ordering:

Old part number: 545150201  
Description: Starter pulley

New part number: **589505501**  
Description: **Pulley service kit**

### Affected Serial Number Range:

All produced prior to May 3, 2017; the serial numbers include all prior to **17123NXXXXX**.

### Serial number format information:

**17** = Year produced

**123** = Consecutive day of the year (123/365)

### Models Affected:

952711937 (FB25)

### If you have questions, contact us.

Husqvarna Dealers call 1-800-448-7543

All other customers call 1-800-487-5951