

## RIDER 850-12

During 1988, the Rider 850 has for the US and Canada been equipped with a cutting blade Ref. No. 506 66 87-01. This blade has not been fully accepted in the North American cutting conditions. For the season 1989, we have therefore developed a new blade with a longer edge and bigger bent tips Ref. No. 506 67 65-01.

When the new blade is mounted, the baffle plate (air conductor) in the cutting deck should also be removed. The baffle is located inside the cutting deck, in the front. In order to remove the baffle, the cutting deck must be removed. The baffle is welded to the cutting deck and therefore a grinding machine or other suitable tool must be used. See illustration. Change of blades and removal of the baffle plate should be made on all Riders of the model 1988.

When reassembling the cutting deck it has to be adjusted according to the Operator's Manual, page 45.

