

CLEARING SAWS

Blade nut 502 04 55-01

A new improved blade nut is introduced. The new nut has a black or a yellow plastic, which locks the nut on the shaft.

This change is introduced in order to even more secure the locking on the shaft and to give an improved locking effect after repeated mountings and removals of the nut.

Ref. No. 502 04 55-01 remains unchanged.

The new nut was introduced in our production and in our spare parts stock from February 1989.

Important! If a decrease of the locking is noticed, the nut must be replaced immediately. (This is also valid for the earlier design). The nut locking should have a locking torque of at least 1.5 Nm (17 in/lb). The torque on the nut should be 35-50 Nm (25-36 ft/lb).