

Model 265RX

Improved seal of blade shaft

To make it harder for dirt and grass to enter the gearing and destroy the seal and bearing the gap between the driver and the gear housing cover has been reduced from serial number 626 0067.

Driver 502 25 41-02 also fits in gear housing cover 502 10 72-02.

Driver 502 25 41 -01 does not fit in gear housing cover 502 10 72-03.

If the gear housing cover 502 10 72-03 is fitted to the gear box 502 10 70-03 then the driver must also be changed to the later design.

New Ref. No.	Description	Excl. Ref. No.	Remark
502 10 70-05	Gear assy.	502 10 70-03	
502 10 69-03	Gear housing cover compl.	502 10 69-02	R
502 10 72-03	Gear housing cover	502 10 72-02	R
502 25 41-02	Driver	502 25 41-01	R

R = remains as a spare part

Other parts remain as previously.

