

## SB, SC18 A, Blade cable-pull, 2007-06

Models Affected: All SC18A Sod Cutter

In our overall effort to improve product quality, the blade-pull cable has been increased in strength and diameter. A kit has been established with the correct hardware for installing the new cable. It is part number 539 13 06-26. This replaces the old cable which was 539 11 33-79. Please change your manual to reflect this change. The kit has some additional hardware complete with assembly instructions. There is also new grade 8 hardware to attach the blade with torque specifications included in the kit. This cable only applies to SC18A not SC18.

Warranty Information: warranty will be paid for replacement of part upon failure and a labor rate of ½ hour.