

SB, Mulch Plate kit, TS 343, 2016-09

Affected models

Model	PNC
TS 343	960 41 03-89

Affected serial number(s)

All 2016.

Description

Due to a mistake in the BOM (Bill of Material) creation process for the model TS 343 / 9604103-89 of Model Year 2016, the mulch plate was not included in the packaging. The tractor model is equipped with combi type blades designed for side discharge / mulch (BioClip™), so there is no need for a special mulch blade.

Action

To correct the mistake, it will within short be possible to order a kit; 589 65 96-01. This kit will be available at no cost and fits this tractor model only.

The 2017 model year production of this tractor model will contain the mulch plate.

Parts information

New part no.	Part description	Old part no.
589 65 96-01	Mulch Plate kit	N/A
960 71 00-47	Collector	N/A
960 71 00-46	Hi lift blade kit	N/A

Warranty reporting

Warranty type:	Normal warranty applies (replace when broken)
Residual stock:	N/A
Component code:	602 Brackets / Support
Defect code:	20 Missing
Warranty report text:	B160038
Time units (6 minutes):	1 unit
Affected markets:	All

Additional information

We recommend the following combination of accessories for collecting with this model:

2-bin Collector: 960710047 – Collector.

If mowing in tougher grass conditions – we also recommend to change blades for extra grass flow: 960410046 - Hi lift blade kit.