


## ROYAL 46

### NEW BLADE (516 50 64-00)

Some early machines have been delivered with a too long blade which can hit the deck during starting operation.

The new number for the blade is 516 50 64-00. Please change the number in your spare parts list.

The correct length is 456 mm.



### Printing error in the spare parts list square E

Ref. No. 516 44 83-01 shall be 516 44 83-00

Ref. No. 516 44 37-01 shall be 516 44 37-00

Please change the numbers in your spare parts list accordingly.